




Cordless Tool Storage

Cutting Diagram

48" x 96" - 1/2" PLYWOOD



Materials

Storage Cabinet

A Sides (2)	12 ¹ / ₂ x 24 ¹ / ₂ - 1/2 Plywood
B Shelves (2)	10 ¹ / ₂ x 20 - 1/2 Plywood
C Bottom (1)	11 x 20 - 1/2 Plywood
D Back (1)	20 x 24 ¹ / ₄ - 1/2 Plywood
E Support (1)	10 ¹ / ₂ x 8 ¹ / ₄ - 1/2 Plywood Platform
F Platform (1)	9 ¹ / ₂ x 10 ¹ / ₂ - 1/2 Plywood Upright
G Drawer Front/Back (2)	2 ¹⁵ / ₁₆ x 19 ⁷ / ₁₆ - 1/2 Plywood
H Drawer Sides (2)	2 ¹⁵ / ₁₆ x 10 - 1/2 Plywood
I Drawer Bottom (1)	10 x 18 ¹⁵ / ₁₆ - 1/4 Hardboard
J Cleats (2)	1 ¹ / ₂ x 3 - 19 ¹ / ₂ Hardwood