



Horizontal Mortising Machine

Materials

Tapered Bed


A Base (1)	20 x 24 - $\frac{3}{4}$ " Plywood
B Sides (4)	5 x 16 - $\frac{3}{4}$ " Plywood
C Adjustment Blocks (2)	2 $\frac{3}{4}$ x 6 $\frac{1}{2}$ - $\frac{3}{4}$ " Plywood
D Top (1)	9 $\frac{1}{2}$ x 16 - $\frac{3}{4}$ " Plywood

Sliding Table

E Table (1)	9 $\frac{1}{2}$ x 23 $\frac{3}{4}$ - $\frac{3}{4}$ " Plywood
F Handles (2)	1 x 9 $\frac{1}{2}$ - $\frac{3}{4}$ " Plywood
G Cleat (1)	3 x 12 - $\frac{3}{4}$ " Plywood
H Spacer (1)	1 x 7 $\frac{1}{2}$ - $\frac{3}{4}$ " Plywood

Carriage

I Front (1)	12 $\frac{1}{4}$ x 12 - $\frac{3}{4}$ " Plywood
J Back (1)	12 $\frac{1}{4}$ x 4 - $\frac{3}{4}$ " Plywood
K Sides (2)	12 x 12 - $\frac{3}{4}$ " Plywood
L Bottom (1)	11 $\frac{3}{4}$ x 10 $\frac{1}{2}$ - $\frac{3}{4}$ " Plywood
M Clamp Blocks (2)	2 $\frac{1}{2}$ x 11 $\frac{1}{4}$ - $\frac{3}{4}$ " Plywood
N Lever Arm (1)	1 $\frac{1}{2}$ x 17 - 1 $\frac{1}{2}$ " Plywood
O Lever Arm Block (1)	2 x 4 - 1 $\frac{1}{2}$ " Plywood



48" x 48" - $\frac{3}{4}$ " PLYWOOD