

# ShopNotes Cutting Diagram

## Roll-Around Tool Cart

### Materials

#### Case

A Sides (2)	$15^{13}/16 \times 26^{1}/4$ - $3/4$ Plywood
B Divider (1)	$15^{9}/16 \times 26^{1}/4$ - $3/4$ Plywood
C Skins (4)	16 rgh. x $26^{1}/2$ rgh. - $1/4$ Hdbd.
D Top/Bottom (2)	$15^{9}/16 \times 27$ - $3/4$ Plywood
E Back (1)	$26^{1}/4 \times 27^{1}/2$ - $1/4$ Hardboard

#### Doors/Worksurface

I Door Panels (2)	$13^{1}/2 \times 25^{11}/16$ - $3/4$ Plywood
J Edging	$1/4 \times 3/4$ (20 Linear Ft.)
K Trim Strip	$3/16 \times 3/4$ (7 Linear Ft.)
L Top Panel (1)	$16^{3}/4 \times 28$ - $3/4$ Plywood


#### Tool Trays

F Bottom (6)	$12^{13}/16 \times 15^{9}/16$ - $1/4$ Hardboard
G Front/Back (12)	$3/4 \times 2 - 11^{1}/4$
H Sides (12)	$3/4 \times 2 - 15^{9}/16$


$1/4 \times 48 \times 96$  HARDBOARD



3/4 X 48 X 96 BIRCH PLYWOOD



3/4 X 5 X 96 HARDWOOD



3/4 X 5 X 96 HARDWOOD

